## Message Text

LIMITED OFFICIAL USE

PAGE 01 STATE 051063

70

**ORIGIN FBO-05** 

INFO OCT-01 AF-06 ISO-00 SY-05 A-01 /018 R

DRAFTED BY A/FBO:CHALSPAUGH:ADW APPROVED BY A/FBO:CVSWAN A/SY/FO:MMULVEY (PHONE)

----- 096593

P 022332Z MAR 76 FM SECSTATE WASHDC TO AMEMBASSY LAGOS PRIORITY

LIMITED OFFICIAL USE STATE 051063

E.O. 11652: N/A

TAGS: ABLD, AFSP, ASEC

SUBJECT: BUILDING REPAIRS - CHANCERY

REF: LAGOS 2161

- 1. REPLACEMENT OF EXISTING WINDOW GLASS WITH LEXAN WOULD BE PROHIBITIVELY EXPENSIVE AND WOULD REQUIRE REPLACING FRAMES AS WELL TO ACCOMMODATE THIS THICK MATERIAL.
- 2. NO OBJECTION TO BRICKING UP WINDOW AREAS AND INSTALLING H-6 GLASS (5/16 INCH THICK) OR 1/4 INCH PLEXIGLASS IN REDUCED AREA. HOWEVER, POST REQUESTED TO ADVISE WHETHER PRESENT FRAMES WOULD ACCEPT EITHER THICKNESS. FORWARD DETAILED WALL SECTION SHOWING RELATIONSHIP BETWEEN ALTERED WINDOW FRAME AND NEW WALL FOR FBO APPROVAL.
- 3. ALTERNATIVELY, PRESENT WINDOW AREAS MAY BE GLAZED IN WITH EITHER H-6 GLASS OR 1/4 INCH PLEXIGLASS PROVIDED PRESENT FRAMES WILL ACCEPT.
- 4. IN EITHER CASE, PLEASE PROVIDE DIMENSIONS OF ACTUAL GLASS SIZE AND QUANTITIES REQUIRED. INGERSOLL LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 02 STATE 051063

LIMITED OFFICIAL USE

NNN

## Message Attributes

Automatic Decaptioning: X Capture Date: 01 JAN 1994 Channel Indicators: n/a

**Current Classification: UNCLASSIFIED** 

Concepts: n/a Control Number: n/a Copy: SINGLE Draft Date: 02 MAR 1976 Decaption Date: 01 JAN 1960 Decaption Note: Disposition Action: RELEASED

Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Authority: morefirh
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 28 MAY 2004
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1976STATE051063

Document Number: 1976STATE051063
Document Source: CORE
Document Unique ID: 00 Drafter: CHALSPAUGH:ADW

Enclosure: n/a Executive Order: N/A Errors: N/A

Film Number: D760079-1016

From: STATE

Handling Restrictions: n/a

Image Path:

Legacy Key: link1976/newtext/t197603102/aaaadmdz.tel

Line Count: 60

Locator: TEXT ON-LINE, ON MICROFILM Office: ORIGIN FBO

Original Classification: LIMITED OFFICIAL USE

Original Handling Restrictions: n/a
Original Previous Classification: n/a Original Previous Handling Restrictions: n/a

Page Count: 2

Previous Channel Indicators: n/a
Previous Classification: LIMITED OFFICIAL USE

Previous Handling Restrictions: n/a Reference: 76 LAGOS 2161

Review Action: RELEASED, APPROVED Review Authority: morefirh

Review Comment: n/a
Review Content Flags: Review Date: 06 JUL 2004

**Review Event:** 

Review Exemptions: n/a
Review History: RELEASED <06 JUL 2004 by ellisoob>; APPROVED <07 JUL 2004 by morefirh>

**Review Markings:** 

Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 04 MÁY 2006

**Review Media Identifier:** Review Referrals: n/a Review Release Date: n/a Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

Secure: OPEN Status: NATIVE

Subject: BUILDING REPAIRS - CHANCERY

TAGS: ABLD, AFSP, ASEC To: LAGOS

Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 04 MAY 2006